

How to send instruments in for Calibration:

Print and fill out [return goods form](#).

Securely pack instrument in cardboard box or Airmold case. Airmold case will be shipped back locked, so please let us know if you need a key.

- Put return goods form in with instrument (be sure to include contact, Phone# and PO# on R.G.F)
  - Ship UPS, Fed Ex, Airborne or US mail to: Suntrac Services 1818 East Main St. League City TX 77573
  - All packages will be shipped back UPS ground service unless otherwise specified.
  - We can ship packages back Fed Ex or Airborne using your account number.
  - We do not give Return Authorization Numbers for return shipments
-